## ONRSR Reporting Quick Reference Guide

## PROCEED AUTHORITY EXCEEDED

(including SPAD's)



Definition

A proceed authority exceedance is when a train exceeds the limit of authority, a train proceeds without a proceed authority or proceeds whist a restraint authority is in place.

CAT

A ₹

Immediate

A train (except a light rail vehicle) has exceeded a limit of a proceed authority or proceeded without proceed authority on or onto a running line due to:

- · the driver completely missing the limit of authority; or
- that resulted in the train entering an occupied section of track or in conflict with another train movement.

A train (including a light rail vehicle) has exceeded a limit of a proceed authority or proceeded without proceed authority on or onto a running line that resulted in the train:

- entering a work site; or
- entering an active level crossing without warning devices activating.

A train (including a light rail vehicle) proceeds whilst a restraint authority is in place.

CAT

Annual

A train (including a light rail vehicle) that has exceeded a limit of a proceed authority or proceeded without authority:

- where the rear portion of an otherwise stationary train (excluding a light rail vehicle) rolls back, resulting in part of the rear vehicle re-occupying a section; or
- within a yard and the train has remained in the yard; or
- all other exceed authority not categorised as a Cat A or B.

B

**72hrs** 

A train (except a light rail vehicle) has exceeded a limit of a proceed authority or proceeded without proceed authority on or onto a running line other than roll back.

Not Reportable to ONRSR

• A driver is given a correct and valid proceed authority to move past the limit of authority (e.g. to pass a signal displaying a danger aspect).